

ERT - Simulacro / ERT - Drill: Run on 02/05/2022

This document was created in MY Compliance Management on 20/09/2022 14:35:36

Audit Details

Audit name:	ERT - Simulacro / ERT - Drill
Audit date:	02/05/2022
Auditor:	David Pinto
Audit details:	Simulacro en áreas de trabajo / Work Area Drill
Overall Outcome:	Completed
Emergencia / Emergency	Accidente vehicular o atropello / Vehicle accident or run over
Breve descripción del evento / Brief Event Description	01 de mayo Concentraducto coastal Road Km 6, Services PP Ops
	Vehiculo colisiona la linea del concentraducto en el KM 6 vía a Puerto, con 1 herido y produciendo fuga de concentrado.
	01 de mayo Concentraducto coastal Road Km 6, Services PP Ops
	Vehiculo colisiona la linea del concentraducto en el KM 6 vía a Puerto, con 1 herido y produciendo fuga de concentrado.
Especificar ubicación / Specify Location	Km 6 Linea de Concentrado
Hora de inicio / Starting Time	15:25
Hora de finalización / Ending Time	15:46
Departamento / Department	PP OPS - Services

Notes

01 de mayo 2022, Linea de Concentraducto Km 6. Colision de vehiculo Tipo Pick Up contra linea de concentrado, produciendo fuga de la linea de concentrado y el conductor herido

May 1, 2022, Linea de Concentraducto Km 6. Vehicle collision Type Pick Up against concentrate line, producing concentrate line leak and injured driver

Response Summary

Section	Completed	Not completed
Audit	1	0

Audit Criteria

#	Criteria	Details	Response
1	Completed Drill	Responsible will determine the drill	Completed

Signatures

ERT - Simulacro / ERT - Drill: Run on 02/05/2022

This document was created in MY Compliance Management on 20/09/2022 14:35:36

Capacity: supervisor

Name: David Pinto

Handwritten signature: D. Pinto

Documents



[fae30bee-e133-4abe-803f-f167ded44066.jpg](#)



[fabe1346-7a75-42d8-874b-0618ee05c41d.jpg](#)

[DOC - Drill Plan Guidance Form 2022 Concentraducto 01 mayo 2022.doc](#)

[DOC - Simulacro de Linea de concentrado 1.5.2022.doc](#)